

GE Renewal Parts

Use original equipment parts for reliability


PARTS BULLETIN


DRILLING MOTOR MODEL 5GE752UB3B


AUGUST 24, 1993


[©] Copyright 1993 General Electric Company. All rights reserved. This copyrighted document may be reproduced free of charge by General Electric Company customers, if such reproduction is used exclusively in connection with equipment used in that customer's internal operation.


DRILLING MOTOR MODEL 5GE752UB3B











DRILLING MOTOR MODEL 5GE752UB3B

FIG.	REF.		QUANT REQ. COL.	
NO.	NO.	PART NO.	A A	DESCRIPTION
1	1	5GE752UB3B	1	DRILLING MOTOR
1	2	41D735775G7	1	ARMATURE ASSEMBLY
L	3	41C636927G1	1	ARMATURE SHAFT WITH PLUGS
1	4	8819420P1	2	PLUG, HEX SOC HD, 3/8 IN-24, 1 IN LONG
l	5	41B537605P4	1	ARMATURE HEAD
l	6	41B537889G2	1	COMMUTATOR, SEASONED
L	7	41B537164P1	553	PUNCHING, MAIN
L	8	41B537165P2	14	PUNCHING, STEP BACK
L	9	41B537165P1	26	PUNCHING, STEP BACK
L	10	41A239323G1	1	PUNCHING, END
L	11	41A330418G1	1	PUNCHING, END
L	12	41D735370G5	1	ARMATURE REWIND KIT
L	13	41A330208P10	AR	WIRE, 0.072 IN DIA
1	14	41B537080P1	1	=TEFLON BAND (CONTINUOUS)
L	15	41A239176P64	AR	GLASS TAPE, 0.014 IN THICK, 3/4 IN WIDE
L	16	186V989P1	1	SLEEVE
L	17	2766829ADP24	AR	#BALANCE WEIGHT, 13 IN OD
L	18	2766829ADP26	AR	#BALANCE WEIGHT, 14 3/4 IN OD
	19	41A323821P1	1	ADAPTER
L	20	41C633493G1	1	FRAME HEAD ASSEMBLY
L	21	481A560G1	1	FLASH RING
l	22	N22P29020B13	6	#BOLT, HEX HD, 1/2 IN-13, 1 1/4 IN LONG
l	23	493A546P1	1	GASKET, 0.021 IN THK
L	24	41B532420P1	1	BEARING CAP
L	25	493A540P1	1	SLEEVE
Ĺ	26	N405P47B13	8	LOCKWASHER, 5/8 IN
L	27	N22P33044	8	BOLT, HEX HD, 5/8 IN-11, 2 3/4 IN LONG
l	28	41C633494P1	1	BEARING HOUSING
L	29	8864951P147	1	ROLLER BEARING
L	30	2739317P1	1	BEARING CAP
_	31	4732351P1	1	SLEEVE
- [32	4732906P1	2	GASKET, 0.021 IN THICK
	33	N22P33056	8	BOLT, HEX HD, 5/8 IN-11, 3 1/2 IN LONG
	34	41B537660P9	8	WASHER, FLAT, 0.725 IN ID, 1 IN OD
	35	41C637314P1	1	FRAME HEAD
	36	8864951P167	1	ROLLER BEARING
	37	4713640P1	1	FLINGER
_	38	6744700P2	1	BEARING CAP, INNER
- [39	41B537963P1	12	CARBON BRUSH
- [40	41B537660P21	11	WASHER, FLAT, 1.063 IN ID, 2 IN OD
<u>.</u>	41	N22P39032	11	BOLT, HEX HD, 1 IN-8, 2 IN LONG

[#] WELD OR BRAZE IN POSITION.

⁼ ADDITIONAL MATERIAL IS REQUIRED TO INSTALL THE CONTINUOUS LOOP TEFLON BAND. SEE APPLICATION INSTRUCTIONS, GEK-76278.

DRILLING MOTOR MODEL 5GE752UB3B

FIG	DEE		QUANT REQ.	
FIG. NO.	REF. NO.	PART NO.	COL. A	DESCRIPTION
1,2,3	42	41C632667G6	4	BRUSH HOLDER ASSEMBLY
3	43	41B530659G2	12	PRESSURE ARM
3	44	41A231370P2	12	BUSHING, 1.063 IN LONG
3	45	186V831P1	8	SLEEVE
3	46	41A231378P2	4	PIN, 3/8 IN DIA, 6 5/8 IN LONG
3	47	N509P2548	8	PIN, SPRING DOWEL, 1/4 IN DIA, 3 IN LONG
3	48	N509P912	8	PIN, SPRING DOWEL, 3/32 IN DIA, 3/4 IN LONG
3	49	41A230733P7	8	BOLT W/WASHER, HEX HD SL, 5/16 IN-18, 3/4 IN LONG
3	50	41A231370P6	16	BUSHING, 0.575 IN LONG
3	51	41B537844G1	12	SPRING SET ASSEMBLY
3	52	41A233880P1	4	PIN, 7 7/16 IN LONG
3	53	41B535754G28	8	BRUSH HOLDER STUD, MOLDED (0.002 IN OVERSIZE)
3	54	41B535754G29	8	BRUSH HOLDER STUD, MOLDED (0.004 IN OVERSIZE)
3	55	41B535754G30	8	BRUSH HOLDER STUD, MOLDED (0.006 IN OVERSIZE)
3	56	41B535754G31	8	BRUSH HOLDER STUD, MOLDED (0.008 IN OVERSIZE)
3	57	41A330248P1	12	SPRING SEAT
3	58	41A233867G4	12	SPRING SEAT WITH PIN
l	59	2733755P7	4	SUPPORT, BRUSH HOLDER
l	60	41B537660P25	4	WASHER, FLAT, 0.968 IN ID, 1.375 IN OD
1	61	N22P37052	4	BOLT, HEX HD, 7/8 IN-9, 3 1/4 IN LONG
2	62	41C636243G2	2	CABLE ASSEMBLY
2	63	41B531137G10	1	CABLE ASSEMBLY
2	64	41B531137G7	1	CABLE ASSEMBLY
2	65	481A539P32	2	CABLE BUSHING, 1 7/32 IN ID, RUBBER
2	66	41A210359P12	2	REDUCING BUSHING, 1 1/2 IN TO 3/4 IN
2	67	41D735504G7	1	SHUNT ASSEMBLY
2	68	41C637562G3	1	CABLE ASSEMBLY
2	69	41C637562G4	1	CABLE ASSEMBLY
2	70	4713845P1	1	BOLTING PLATE
2	71	N22P27020B13	10	BOLT, HEX HD, 7/16 IN-14, 1 1/4 IN LONG
<u> </u>	72	N405P44B13	12	LOCKWASHER, 7/16 IN
2	73	41A230733P4	8	BOLT W/WASHER, SL HX HD, 1/4 IN-20, 1/2 IN LONG
<u>-</u> 2	74	8809650P1	8	WASHER, CONCAVE, 1/4 IN, SPR STL
2	74 75	N203P21B13	8	NUT, HEX, 1/4 IN-20
2	75 76		AR	SEALANT, 1/8 BY 3 3/4 IN, 10 FT ROLL
<u>^</u> 2	76 77	41A216775P1 N22P27028B13	2	BOLT, HEX HD, 7/16 IN-14, 1 3/4 IN LONG
			AR	SILASTIC PUTTY
2	78 70	41A239176P443		
2	79	41A239176P133	AR	SILICONE TAPE, 0.015 IN THICK, 1 IN WIDE
2	80	41A239176P22	AR	GLASS TAPE, 0.007 IN THICK, 1 IN WIDE
2	81	41A239176P487	AR	VARNISH
2	82	N22P33028	1	BOLT, HEX HD, 5/8 IN-11, 1 3/4 IN LONG
2	83	N213P33	2	NUT, HEX, JAM, 5/8 IN-11
2	84	N405P47B13	2	LOCKWASHER, 5/8 IN

FIG. NO.	REF. NO.	PART NO.	QUANT REQ. COL. A	DESCRIPTION
2	85	N22P33024	1	BOLT, HEX HD, 5/8 IN-11, 1 1/2 IN LONG
2	86	41C637285G10	2	COIL WITH POLE PIECE, COMMUTATING
2	87	41C637285G11	2	COIL, COMMUTATING
2	88	41C637285G7	2	COIL WITH POLE PIECE, COMMUTATING
2	89	41C637285G8	2	COIL, COMMUTATING
2	90	8855483G4	4	COIL WITH POLE PIECE, EXCITING
1,2	91	41B537660P22	24	WASHER, FLAT, 1.453 IN ID, 2.500 IN OD
1,2	92	N22P45060	12	BOLT, HEX HD, 1 1/4 IN-7, 3 3/4 IN LONG
1,2	93	41A239559P1	12	BOLT, HEX HD, 1 1/4 IN-12, 4 IN LONG
2	94	8842961G1	3	CABLE ASSEMBLY
2	95	41C637261G1	1	CONNECTION STRAP, INSULATED
2	96	41C637261G2	1	CONNECTION STRAP, INSULATED
2	97	41A231281P47	7	BRAZING STRIP
2	98	41A330300P2	AR	BRAZING ALLOY, 0.050 X 0.062 IN
2	99	41C637261G5	1	CONNECTION STRAP, INSULATED
1	100	493A204G1	1	INSPECTION COVER, TOP
1	101	493A204P3	2	GASKET, NEOPRENE, 0.250 X 0.750 X 9 3/4 IN LONG
1	102	493A204P4	2	GASKET, NEOPRENE, 0.250 X 0.750 X 11 IN LONG
1	103	497A806P12	AR	CEMENT
1	104	493A206G1	1	INSPECTION COVER, BOTTOM
1	105	493A206P3	2	GASKET, NEOPRENE, 0.250 X 0.750 X 9 1/2 IN LONG
1	106	493A206P4	2	GASKET, NEOPRENE, 0.250 X 0.750 X 11 1/8 IN LONG
1	107	497A806P12	AR	CEMENT
1	108	41A239914G1	1	INSPECTION COVER, HAND HOLE
1	109	41A239914P2	2	GASKET, 9 1/4 IN LONG, 1/4 IN THICK
1	110	41A239914P3	2	GASKET, 8 1/8 IN LONG, 1/4 IN THICK
1	111	497A806P12	AR	CEMENT
1	112	N14P29020B13	4	BOLT, HEX HD, 1/2 IN-13, 1 1/4 IN LONG
1	113	N405P45B13	4	LOCKWASHER, 1/2 IN
1	114	41A239663P2	4	PLUG
		N5700P63	5	PIPE PLUG, 3/4 IN, CSK SQ HD

- END OF PARTS BULLETIN -